*RECEIVING INSPECTION, REPORT Approved For Release 2008/04/48 COLA-RDP81B00879R000500080168-28 1941 E. COLORADO ST., PASADENA, CALIF. FROM DATE REC'D: 4-8-57 PLAST #9 VENDOR PACKING SLIP NO DRAWING NUMBER DWG DASH OR CLASS. OPER NUMBER CODE HO. CHARGE TO S.O. NO ... QUANTITY QUANTITY DRAWING NO. AND DESCRIPTION ACCEPTED REJECTED. Solonoid Vac. 10 737778-2 RECEIVING INSPECTION REPORT No. 11861 HYCON MFG. COMPANY 2961 E. GOLORADO ST., PASADENA, CALIF. DATE REC'D. RECEIVED FROM PLANT A VENDOR PACKING SLIP NO BUY OUT CONTRACT LOT NO. CLASS NUMBER DWG. OFFI ACCT. OR 23 CHANGE TO QUANTITY RECEIVED QUANTITY DRAWING NO. AND DESCRIPTION ACCEPTED REJECTES Clutch Housing Lably 10 731720-0

CONTRACT DRAWING DAYS FOR DWG LOT CLASS OF CITY OF DAYS FOR DWG LOT CODE NO DWG LOT CODE

RDP81B00879R000500080163-3

Approved For Release 2009/04/18